ICS 209 (Oil Spill) - Incident Status Summary Incident Name: South 4 Group Fire				Version Name: 20191213 Period: Period 14 [12/14/2019 06:00 - 12/17/2019 06:00]								
Spill Status (Estimated)				Equipment Resources								
Source Status Remaining potential			1	51,740		Ordered		Assigned	Out-Of-	Tota		
SECURED		of spillage				arrel(s)	T T T T T T T T T T T T T T T T T T T	Olueleu	Available	Assigned	Service	1
OLOGINED		nes meas				arrel(s)	Air Monitor - AreaRAE	0	0	31	0	31
			Last R	enort		Total	Air Monitor - MultiRAE	0	0	81	0	81
Total Volume	Snilled	Jilice	Lastin	0		999	Air Monitor - UltraRAE	0	12	43	0	55
Mass Baland	•	atod)		Volume	in		Boom	0	1	11,500	0	11,501
Recovered Mate	•	-T	1	5,000		76,500	Fire Fighting Foam	0	1,590	0	0	1,590
Foam	(Liquiu)			0	***************************************	1,320	J.Ion Boat	0	0	6	1	7
Combusted Mat	orial (bbl)	_		0	***************************************	48,970	4Pumps	2	20	32	0	54
				<u> </u>		40,970	Response Boat	0	0	3	0	(3)
Waste (Estir	nateu)	T D		Starra d			Skimmer	0	17	1	0	18
Type		Recover		Stored E	Disposed	UOM	Sorbent: Boom	0	50	8,350	0	8,400
Sorbent: Boom		12,12			***************************************	Feet	UTV	0	0	9	0	ç
Debris		1,02				Bags	Vacuum Truck	0	0	10	0	10
Liquid		149,3	0			gallon (s)	Vehicle	0	17	143	0	160
Shoreline In	pacts		Di	stances	measu		Viscous Sweep	0	0	250	0	250
	.,,					mile(s)		Personn	el Resou	rces		
Degree of Oil	ling	Affe	cted	Cleaned	1	aining to Cleaned	Organization	Peop	le in the Field	People Cmd. P		al People On Scene
		Wildlife II	npacts				Other		2		0	2
					Died In	Facility	Federal		17		16	33
Туре	Captured	Cleaned I	Released	DOA	Euth.	Other	State		8		3	11
Fish Above 3"	0	0	0	68	0	0	Local		5		1	6
Bird	0	0	0	0	0	0	RP		137		47	184
Mammal	0	0	0	0	0	0	Contract Personnel		492		85	577
Reptile	0	0	0	1	0	0	Volunteers		0		0	C
2-3" Fish	0	0	0	2,000	0	0	Totals		661	1	52	813
Blue Crab	0	0	0	18	0	0		Spec	ial Notes	3		
		Safety S	tatus	1			Active Fires: 2	•				
Туре		Amour	t since la	st report	Total	'Amount	h - 4					
Public Injury				0	***************************************	0	Notes:					
Responder Injur	v		***************************************	0	***************************************	4	*Spilled material based o	n 98% dest	ruction effic	ciency of th	e fire.	
Community Air I		r		9,557		80,000						
BD - Community Air Detections above action level		0		239								
Community Air Monitoring readings for Butadiene				25,233								
VOC - Community Air Detections above action level			0		12							
Community Air I readings for VO						25,489						
ICS 209 (Oil	CS 209 (Oil Spill) - Incident Status Summary			Prepared By Planning	g Section, I	Jpdated 1	2/13/2019	23:16 U	TC -6: PF			
INCIDENT ACTIO	N DI AN COI	ETWADE™	Drinted 1	2/13/2019 2	2:10 LITC	6:00	1 of 6		T			© TRG

Daily Summary – TPC Port Neches South 4 Group Fire 12/13/2019

The waterway has now transitioned to Maintenance and Monitoring Mode

Shoreline Impacts	Assessed, miles	In Remediation, miles	Sign Off
No Oil Observed	4.96		4.96
Light Oil	1.05		1.05
SCAT Recommends No	2.58		2.58
Further Treatment			

Today's Activities

- DEHA was not injected into any tanks 12/13/2019.
- Surveys conducted using FLIR camera identified additional leaks. The leaks were located on lines associated with the following:

Tank Number	Material in Tank	Component Involved	Repaired
39	Raffinate	Flange on line	12/13/2019
40	Raffinate	Tubing valve	
36	High Butane Raffinate	Flange on tank	
33	High Butane Raffinate	Tubing fitting	
35	High Butane Raffinate	Tubing leak	
90 & 91	High Purity Butadiene	Common suction line leak	
26	Crude C4	Line leak, attempted repair	
		with clamp	
30	Water and NMP Solvent	Tubing fitting	12/13/2019

- The FLIR survey revealed the low volume vapor leak from Tank 33, which is inaccessible for safety reasons, may be associated with a line located under the tank. The leak is ongoing. The cribbing contractor and TPC Technical team are developing parallel plans for securing the tank and mitigating the leak after the tank is secured.
- The SCAT Assessment Team, consisting of a multi-agency group that includes EPA, US Coast Guard, General Land Office, TCEQ, TPWD, County and Local agencies, observed the waterways and determined the conditions met the agreed upon endpoints to transition into Maintenance mode.
- The drone completed the ORTHO evaluation (recording current images in high definition).
- 168 hours without wildlife hotline calls. Wildlife Response personnel on call, no EOC presence.
- There was no stormwater discharge via Outfall 201. The water level in the plant remains 2 feet below the weir.
- The waterways are in maintenance and monitoring mode. There were no issues identified 12/13/2019

Upcoming Activities

- Continue to develop a plan for addressing Tank 33's stabilization and leak mitigation
- Securing Tank 33 and implement the Cribbing Plan and the Leak Mitigation Plan.
- Daily school air monitoring is continuing
- TPC assisting neighboring plants to ensure their utilities are available.

Health and Safety

No issues to report

Water Effluent

- Status of 201: No Flow, 1.5 feet below the weir
- GPM to JWWTP: 0 gpm, building level in Block 6 ponds

Water Testing: 12/13/2019 No new results.

- Since December 7, 2019, an estimated 133 surface water samples have been collected from 17 different
 locations for VOCs, SVOCs, PAH, PFAS, TPH, TOC, oil and grease, ethylene glycol, and asbestos analysis. Results
 of these analysis are not representative of drinking water sources. There are no drinking water sources
 downstream of the waterways.
- There have been no exceedances of TCEQ Contact Recreation Water Protective Concentration Limit (PCL) screening levels for the surface water samples with available PCLs. Where no PCLs are available, results are being compared to background surface water samples. There are no drinking water sources downstream.
- EPA provided additional criteria for screening the results. That comparison is being conducted.

Wildlife Report

None

Recovery Operations

No changes

SCAT Report

• Maintenance and Monitoring Plan is in effect. No issues identified for today.

Waste

12/13/2019 No changes in volumes Some analytical results were received for waste classification.

Gallons	Frac Tanks (20,000 gallons capacity)	# Of Tanks Used
137,000	Liquids from outfall canal skimming	7
5,000	Water and hydrocarbons from south separator	0.25
30,000	Latex-laden Wastewater from LION	1.5
	Empty Available and Staged	6
172,000	Totals	16

CYD's	Roll Off Boxes (25 CYD's capacity)	# Of Boxes Used
162.5	Hydrocarbon Debris and Sorbents From Canal	6.5
162.5	Totals	7

Empty available and staged (requested 4 more) 3

CYD's	Potential Asbestos Containing Material (PACM)	# Of Boxes Used
12.5	Material from 201 outfall and south separator	0.5
25	Motiva (1-full, 1-in use)	2
	Joint Waste Water (have not begun using yet)	1
37.5	Totals	4

Other	
Routine Plant Trash (Garbage)	1
Dirty Containment Boom waiting on decon	1

Community Air Monitoring

Asbestos Monitoring

Community

- Wipe samples: Zero of the 180 samples collected have been positive for asbestos
- Bulk Sampling: 96 of 234 samples tested positive for asbestos

Air Monitoring Sampling Results

Community

No analytical updates available at the time of this report.

Analytical	Detections	Samples Collected	Sample Stations
Volatile Organic Compounds (VOC)*	2*	362	48
Poly Aromatic Hydrocarbons (PAH)	None Detected	481	28
Asbestos	None Detected	618	44

^{2*} There were detectable amounts of VOC, but two were above the Texas Commission on

Quality (TCEQ) 24-hour AMCV (430 ppb), however below the TCEQ short-term AMCV (1,700 ppb).

Community Assessments

Refer to following pages.

Community Assessment Summary

2724	575	299	73
Count of Curbside Assessments Completed	Count of Properties with Observed Damage	Count of Properties with Observed Debris	Count of Industrial Debris Claims Sampled
Community Assessment S	ummary - Jefferson		
1391	536	188	57
Count of Curbside Assessments Completed	Count of Properties with Observed Damage	Count of Properties with Observed Debris	Count of Industrial Debris Claims Sampled
Community Assessment S	ummary - Orange		
1333	39	111	16
Count of Curbside Assessments Completed	Count of Properties with Observed Damage	Count of Properties with Observed Debris	Count of Industrial Debris Claims Sampled

Completed Assessments Property Type Summary

Type	# of Properties
Church	9
Commercial/Business	39
Detached storage building.	1
Empty Lot	62
Industrial Facility	1
Library	1
Multi-family Residence	20
Other Public Area	3
Park	3
Single Family Home	2624
	2763